

Head Office: ARB Corporation Ltd Postal Address: PO Box 105, Kilsyth 3137 Australia Street Address: 42 - 44 Garden Street Kilsyth, Victoria 3137 Australia


A Division Of ARB Corporation Limited

Tel: +61 3 9761 6622 • Fax: +61 3 9761 6807 www.arb.com.au ABN 31 006 708 756

FK27

Toyota Land Cruiser 100 Series IFS Torsion Bar Reinforcing Kit

Part No	QTY	DESCRIPTION
3756657L	1	Bracket L/H/S
3756657R	1	Bracket R/H/S
6151045	4	Bolt M10 x 25 x 1.5
6151066	4	Nut M10 Flanged
4581040	4	Washer Flat M10
4581048	4	Washer Spring M10



	Installation Procedure Remove the torsion bar and anchor arm.
Anchor Arm	LEFT HAND SIDE SHOWN RIGHT HAND SIDE OPPOSITE
	Inspect the lower control arm for fatigue cracks in the area shown. If cracks are present, they must be repaired or the arm replaced before fitting the FK27 kit.
	Slide the 3756657L bracket over the 2 anchor arm mounting bolts.
	Reinstall the torsion bar and anchor arm. Tighten the 2 anchor arm retaining bolts to a torque of 225 Nm / 166 ft.lb

